

CNC OPERATORS

POSITION SUMMARY

CNC Operators are responsible for setting up and operating a computer numerical control (CNC) machine, maintaining quality and safety standards, keeping records as well as maintaining equipment and supplies.

KEY RESPONSIBILITIES

- Operation of the following machinery/equipment that frame Glulam components and CrossLam® CLT
 - Hundegger K2
 - Hundegger PBA
 - Creno (le Creneau Industriel)
- Model effective communication, leadership and partnership with the plants
- Continuously grow and develop your operational knowledge and leadership capabilities by participating in professional development opportunities
- Alignment with Structurlam's values of safety, respect, quality, integrity, open communication and profit

KEY REQUIREMENTS

- Experience operating CNC equipment, preferably similar machines
- Experience in the wood industry
- Good organizational skills

Those of us who live in the Southern Okanagan area of British Columbia consider ourselves to be among the most fortunate. If you enjoy fresh air and outdoor activities, this is one of the best places to live in North America.

If you are ready to be part of changing the way we build in North America and bridging the divide between product and process in the construction industry, please send your resume to:

hr@structurlam.com

Structurlam – A Great Place to Work